

Technical Support  
Knowledge Center Open

# IO Libraries Suite: What has changed in version 14.2?

# Notices

© Keysight Technologies Incorporated, 2002-2020

1400 Fountaingrove Pkwy., Santa Rosa, CA 95403-1738, United States All rights reserved.

No part of this documentation may be reproduced in any form or by any means (including electronic storage and retrieval or translation into a foreign language) without prior agreement and written consent from Keysight Technologies, Inc. as governed by United States and international copyright laws.

## Restricted Rights Legend

If software is for use in the performance of a U.S. Government prime contract or subcontract, Software is delivered and licensed as "Commercial computer software" as defined in DFAR 252.227-7014 (June 1995), or as a "commercial item" as defined in FAR 2.101(a) or as "Restricted computer software" as defined in FAR 52.227-19 (June 1987) or any equivalent agency regulation or contract clause.

Use, duplication or disclosure of Software is subject to Keysight Technologies' standard commercial license terms, and non-DOD Departments and Agencies of the U.S. Government will receive no greater than Restricted Rights as defined in FAR 52.227-19(c)(1-2) (June 1987). U.S. Government users will receive no greater than Limited Rights as defined in FAR 52.227-14 (June 1987) or DFAR 252.227-7015 (b)(2) (November 1995), as applicable in any technical data.

**Portions of this software are licensed by third parties including open source terms and conditions.**

**For detail information on third party licenses, see [Notice](#).**

## Contents

### *IO Libraries Revisions: Suite 14.2*

Keysight IO Libraries Suite 14.2 includes defect fixes and makes the following two changes to improve the compatibility of Keysight 488 with recent releases of third-party software:

- The option to **Enable Keysight GPIB cards for 488 programs** is disabled by default if another vendor's NI-488.2-compatible library is also installed. This reduces the likelihood of error messages from the third-party software. (You can always enable this option and your 488 programs will work correctly, regardless of the presence of third-party software.)
- The default board number for Keysight GPIB interfaces is now zero, to conform to hardcoded board numbers in many NI-488.2 programs.

The following defects have been fixed in version 14.2:

- A communication failure message was sometimes displayed when a USBTMC device was connected, if both Keysight and National Instruments I/O software were installed.
- In some cases when both Keysight and National Instruments I/O software were installed, a call to **viReadSTB** on a USBTMC device could fail.
- In some cases when both Keysight and National Instruments I/O software were installed, USBTMC device communication was disrupted after a **viReadSTB** call on a USBTMC device.
- In some cases, an attempt to send a standard USB control request could cause a call to **viUsbControlIn** to fail.
- In some cases when both Keysight and National Instruments I/O software were installed, interrupts relating to USBTMC devices are not delivered. This could cause failure of various operations on USBTMC devices.
- In some cases when both Keysight and National Instruments I/O software were installed, a Device Clear operation on a USBTMC device could cause a device communication failure.
- In some cases, a Device Clear operation on a non-Keysight USBTMC device could time out, leaving the device in an unknown state.
- Connection Expert was unable to find certain non-Keysight GPIB instruments on the LAN. These instruments were therefore not displayed in Connection Expert's **Search for Instruments on the LAN** dialog box.
- Fatal exception errors were displayed by Keysight Interactive IO in some cases.
- The **viFindRsrc** function did not support specification of global attributes. That support has been added.
- Keysight VEE programs are unable to access Keysight GPIB cards that are assigned a logical unit of 14, 15, 17, or 18. Connection Expert has been modified so that it no longer assigns those logical unit values.
- *All 14.1 patch 1 and 2 fixes are also included in 14.2, but not listed here.*

*Last Updated: 08June, 2006*

