- 8:10: Meeting starts
- 8:11: Confirming that meetings will become bi-weekly
- 8:13: Talking about the VEE instruments and labs 1 and 2. Additionally talking about the python scripting
 - Labs are in VEE Training Materials in the drive
 - Python scripting materials are in a similarly named folder in the drive
- 8:18: Going around the table to see if there are any updates or issues that have occurred
- 8:19: Talking about DLLs
 - Talking about what they are, and how they function
 - Talking about how VEE uses DLLs by importing it
 - Talking about how to export DLLs and how other applications use DLLs
- 8:42: Ending meeting
 - The next meeting will be on April 1st